

*** APPLICATION UPDATE ***

Sugar Truck Dumpers at Capiz Sugar Central, Inc. - Capiz, Philippines



Unprotected



Installation



Protected

Problem: Raw sugar packing around truck dumper cylinder seal area, causing rod scoring, seal failure, and contamination of the hydraulic system

Solution: Install the patented* "SEAL SAVER"* protective cylinder covers

Machinery Reliability Corp. of Muntinlupa City in the Philippines brought this application to our attention in December of 2004. MRC recognized that the "SEAL SAVER"* could help Capiz Sugar Central in controlling downtime associated with the frequent rebuilding and re-chroming of their Sugar Truck Dumper cylinders. Capiz Sugar will not only benefit from extended cylinder life, they will also prevent the intrusion of contaminants into the hydraulic system via the rod wipers. Contamination is responsible for 70% of hydraulic component failures. Keeping pollutants from entering the system will prolong the life of all components involved, resulting in less downtime and fewer expenses incurred for hydraulic maintenance or repairs.

THE "SEAL SAVER"* PROTECTIVE CYLINDER COVER - TAKING PREVENTATIVE MAINTENANCE TO A NEW LEVEL

For more information, machine listings, and photos, please visit our web site at: www.sealsaver.com

FLUID CONTROL SERVICES, INC.

849 PICKENS INDUSTRIAL DRIVE • SUITE #7 • MARIETTA, GEORGIA 30062
PHONE: 770.499.9434 OR 800.683.5189 • FAX: 770.499.0064 • E-MAIL: info@sealsaver.com